



HTTPS Certificate Update does not take effect on Brocade Switch

https://kb.netapp.com/on-prem/Switches/Brocade-KBs/HTTPS_Certificate_Update_does_not_take_effe...

Updated: Fri, 18 Sep 2026 07:18:19 GMT

Applies to

- Brocade Switch
- Fabric OS (FOS) 9.1.1x

Issue

- After successful install of a new HTTPS certificate, webserver continues to present an old certificate
- Attempts to restart the services fail with error:

```
admin> hareboot
Can't do hareboot because system is not ready yet or other LS/HA config is in
progress, rc=-1
```

- Errdump shows the errors:

```
[KSWD-1002], 205/96, FFDC | CHASSIS, WARNING, BrocadeG720, Detected termination
of process mdd:2518., hasm_swd.c, line: 235, comp:insmod, ltime:2026/08/
04-18:19:11:429243
[RAS-1001], 206/97, CHASSIS, INFO, BrocadeG720, First failure data capture
(FFDC) event occurred., ffdcd.c, line: 1102, comp:raslogd, ltime:2026/08/
04-18:19:11:430484
[RAS-5001], 207/0, CHASSIS, INFO, BrocadeG720, Message KSWD-1002 caused FFDC
event, ffdcd.c, line: 1105, comp:raslogd, ltime:2026/08/04-18:19:11:430605
[HAM-1007], 217/98, FFDC | CHASSIS, CRITICAL, BrocadeG720, Need to reboot the
system for recovery, reason: Software Bootup Failure:LS config timed out.,
hasm_iot.c, line: 1569, comp:hamd, ltime:2026/08/04-18:21:26:918053
[HAM-1009], 218/99, FFDC | CHASSIS, CRITICAL, BrocadeG720, Need to MANUALLY
REBOOT the system for recovery - auto-reboot is disabled., hasm_iot.c, line:
1589, comp:hamd, ltime:2026/08/04-18:21:26:918293
```