



No AutoSupport Alert for ISL Down Event

https://kb.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/No_AutoSupport_Alert_for_ISL_Down_Event

Updated: Fri, 18 Sep 2026 07:17:06 GMT

Applies to

- ONTAP 9
- Brocade/Cisco cluster switches

Issue

When an Inter-Switch Link (ISL) down event occurred on a BES-53248 cluster switch, no corresponding AutoSupport (ASUP) alert or email notification was sent to the customer.