



Config Advisor reports NIC Model X1146A is not valid



https://kb.netapp.com/Advice_and_Troubleshooting/Flash_Storage/AFF_Series/Config_Advisor_report...

Updated: Fri, 09 Jul 2021 11:56:08 GMT

Applies to

- AFF A800 systems
- Active IQ Config Advisor v5.8.1

Issue

Config Advisor v5.8.1 reports the following warning for AFF A800 systems:

NIC Model X1146A is not valid for the platform or could not be identified.

Potential Impact : Using unsupported NIC cards for cluster interconnect connections will impact performance and functioning of the cluster switches.

